

380/220V - R21, typ ZUR / JP40/

Z 00:05

WX-R43

WX- R43

WX- R43

WX-R44

380/220V, 50Hz

3x6 ZAO, 66/2,5B

AP 40 x 10

